

STELLITE ALLOY 1

Characteristics.

- They are alloys composed of different proportions of cobalt, nickel, iron, aluminum, boron, carbon, chromium, manganese, molybdenum, phosphorus, sulfur, silicon, and titanium.
- There are different grades and most of the alloys get to have from 4 to 6 of these elements.
- It's a hard coating alloy created to enhanced resistance to metal wearing.
- Resistant to rust, abrasion, and corrosion.
- Used in different applications: machinery parts resistant to acids, lathe tool fabrication, pump sleeves, rotary seal rings, saw blades, turbine blades, etc.

Stellite Alloy 1

- Resistant to rust and reducing atmospheres up to 2100°F.
- Excellent restance to high temperatures



STELLITE ALLOY 1

Shape or Presentation

- Bar
- · Welding wire
- Powder
- Electrods
- Cast parts, etc.

Chemical Composition %

Со	Ni	Fe	С
Balance	3 max	2.5 max	2.45
Cr	Mn	Si	w
31	1	1	13